

PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1502

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1502 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1766

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1766 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1767

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1767 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1768

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1768 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1769

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1769 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1770

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1770 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1773

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1773 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1774

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1774 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1775

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1775 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1776

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1776 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1777

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1777 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1778

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1778 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1779

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1779 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1780

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1780 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1783

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1783 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1784

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1784 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1785

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1785 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1786

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1786 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1787

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1787 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1788

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1788 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1789

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1789 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1790

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1790 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1791

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1791 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1792

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1792 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1793

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1793 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1794

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1794 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1795

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1795 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1796

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1796 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1797

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1797 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1798

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1798 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1799

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1799 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1800

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1800 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1801

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1801 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1802

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1802 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1803

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1803 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1804

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1804 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1805

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1805 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1806

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1806 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1807

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1807 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1808

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1808 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1809

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1809 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1810

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1810 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1978

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1978 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1979

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1979 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1980

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1980 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1981

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1981 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1982

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1982 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1983

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1983 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 1984

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 1984 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 2539

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2539 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 2540

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2540 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 2541

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2541 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 2542

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2542 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

31/01/2025 Ref No: Flagstone City Stage 4D_Lot 2585

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2585 - Flagstone City Stage 4D

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 2702/2024 and 15/01/2025.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1813_SEE Civil_Level 1_Flagstone City Stage 4

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au